

Programmed Feeder and Resin Cleaner
for more efficient water conditioning resin
and brine systems.

Res-Up® Feeders

1. Remove brine tank cover.
2. Attach bracket to Res-Up Feeder (plastic container) and position in brine tank next to brine well as shown in Figure 1 on front of this sheet.
3. Drill $\frac{3}{16}$ " hole in brine well cap for Feeder. Drill two $\frac{3}{16}$ " holes in brine tank, just under rim, for bracket and grommets.
4. Remove Feeder and fill to top with water so the filter stone tube and wick are immersed. Allow to soak 15 minutes or more.
5. Empty container and pull tubing until stone is upright, and resting in bottom of stone well.
6. Insert free end of tube into brine well cap. This end of the tube must be below the bottom level of the Feeder.
7. Re-install Feeder and bracket.
8. Fill plastic container with Res-Up® Cleaner to "Fill Line" on label.
9. Replace cover on container and automatic feeding will occur within a few hours.
10. On S6306 Clear 4.0 oz. there is no filter stone. Make sure knotted wick end is at bottom of container.

Recommended Dosages:
For heavily fouled softener beds use 3-4 oz. per cubic foot for initial cleanup. For preventive maintenance use $\frac{1}{2}$ -1 oz. per cubic foot per regeneration.

Res-Up® Cleaner and Feeder Application Guide

Approx. Resin Bed Size	Delivery Feed	Regeneration Cycle (12 Day Clock)				
		1 Cycle	2 Cycles	3 Cycles	4 Cycles	6 Cycles
1/2 cu. ft.	Light Med. Heavy	Yellow Yellow Yellow	Red Yellow Yellow	Red Red Yellow	Red Red Red	Red Red Red
3/4 cu. ft.	Light Med. Heavy	Yellow Clear Clear	Yellow Yellow Clear	Red Yellow Yellow	Red Red Yellow	Red Red Yellow
1 cu. ft.	Light Med. Heavy	Clear Clear Clear	Yellow Yellow Clear	Yellow Yellow Yellow	Yellow Yellow Yellow	Red Yellow Yellow

Note: Res-Up® is not to be used with Gel Zeolite. In the event the resin bed is initially contaminated you may add quantities of Res-Up® cleaner directly into the brine well to start the cleaning action immediately.

ORDER NUMBER	FEEDER SIZE	FEED COLOR CODE	AVERAGE DELIVERY PER DAY	UNIT CTN.	CTN. WT.
S6303	3 pint	Red Tubing	.27 oz. 8.0 cc	12	7
S6304	3 pint	Yellow Tubing	.40 oz. 12.0 cc	12	7
S6305	3 pint	Clear Tubing	1.00 oz. 30.0 cc	12	7
T6001	1 quart	Res-Up Cleaner		12	33
T6002	1 gallon	Res-Up Cleaner		4	40



Clack Corporation

Form No. 1677
Replaces Form No. 1644
Printed in U.S.A.

4462 Duraform Lane P.O. Box 500
Windsor, Wisconsin 53598-0500 USA
Phone (608) 846-3010 Fax (608) 846-2586